## Locating bushes, stainless steel for status sensor



## Item description/product images



## Description

## **Product description:**

Locating bushes form a locating point for ball lock pins or locking pins and enable these to be securely and precisely engaged herein.

The locating bushes for status sensor have a locknut for installing a Ø3 mm sensor into the bush. The sensor enables electronic feedback as to whether a pin is located in the locating bush or not.

When using several bushes, it can be determined in which one a ball lock pin or locking pin is located.

#### Material:

Locating bush stainless steel 1.4305. Locknut brass.

#### Version:

Locating bush bright. Locknut nickel-plated.

## Note:

The locknut is supplied loose. Max. tightening torque for the locknut: 1.2 Nm.

## Application:

Locating bushes in conjunction with a status sensor enable actuation-dependent process control. In addition, it can be determined whether a ball lock pin or locking pin is in the desired position.

#### Assembly:

The sensor is fastened into the bush using the locknut and then adjusted axially. The locknut is tightened to fixate the sensor in the final position.

The detailed procedure is described in the installation instructions.


## Drawing reference:

Form A: full thread Form B: with thread and collar


# Locating bushes, stainless steel for status sensor



## Item description/product images



## Drawings



## **Overview of items**

## Locating bushes, stainless steel for status sensor

Order No.	Form	Form definition	D	D1	D2	D3	D4	Η	H1	H2	H3	H4	H5	М	Ν	Т	SW
K1842.1105120	A	Full thread	5	-	6	9	3	25	4	10	1,5	16,2	4	M12	1,5	1,5	5
K1842.1106160	А	Full thread	6	-	7,5	12	3	25	5	10	2	17,1	4	M16	2	2	5
K1842.1108160	Α	Full thread	8	-	10	12	3	25	5	10	3,1	18,1	4	M16	2	2	5
K1842.1110240	А	Full thread	10	-	13	18	3	30	6	8	4	17,2	4	M24	2,5	3	5
K1842.1112240	Α	Full thread	12	-	15	18	3	30	6	8	4,8	18,2	4	M24	2,5	3	5
K1842.1116300	А	Full thread	16	-	20	24	3	35	8	11	6	24,2	4	M30	2,5	3	5
K1842.1205120	В	with thread and collar	5	20	6	-	3	20	3	5	1,5	11,2	4	M12	2	2	5
K1842.1206160	В	with thread and collar	6	24	7,5	-	3	20	3	5	2	12,1	4	M16	2,5	2	5
K1842.1208160	В	with thread and collar	8	24	10	-	3	20	3	5	3,1	13,1	4	M16	2,5	2	5
K1842.1210240	В	with thread and collar	10	34	13	-	3	25	5	10	4	19,2	4	M24	2,5	3	5
K1842.1212240	В	with thread and collar	12	34	15	-	3	25	5	10	4,8	20,2	4	M24	2,5	3	5
K1842.1216300	В	with thread and collar	16	40	20	-	3	30	5	10	6	23,2	4	M30	2,5	3	5